Tra	ain#	235	TS# EM 01 20 235 TC1 M1 M2 M3 M4 Process Stage PC10	Inspector	PRASA	and Gibela	Date	7/23/2024	Page	1 of 1	
Item		Demerit Class	Defect Description	Localisation Interior, underframe, roof etc	End [1] or [2]	Side Left [L] or Right [R]	(Ready to fix/	tion Required Part needed/ NCR/ Work quired for special process rework)	Pme,Ops, Warehouse,Design,SQ A	GIBELA Sign-off	PRASA Sign-off
					Quality De	eclarations					
1		С	TC1 Cab end PIS glass is not fitted	INT	1	С		NCR	SQA		
2		С	TC1 and TC2 Missing wiper controller	EXT	1	С	Derogatio	n _PRASA-DERSU-1202	Warehouse		
					Engineeri	ng Defects					
1		С	M2 LV4 cubicle side cover has a gap above 3.5mm	INT	1	L	As Pe	er DPM Discussion	ENG		
					Quality	Defects					
1		С	TC1 RHS Cab door key cover is not fitted	EXT	1	R		RTF	Global		
2		С	TC1 and TC2 Foot rest not working	INT	1	С		NCR	SQA		
3		С	Crack on the bottom hinge: M1 LV3.1 cubicle M2 End 1 LV6 cubicle M2 End 2 LV 3.1 cubicle IC1 End 2 HC cubicle	INT	1+2	R+L		NCR	BFG		
		Date									
	~~	3								30/05/2022	

	1 Defects Report 30/05/2022
4/5 Pages	Alb Pages