

Train #	240	Car #	M3	TC1	M1	M2	M3	M4	TC2	Process Stage	Inspector	Nile huda	Date	12/03/2017	Page	4/5	
Item Code	Defect Code	Dement Class	Description of Defects								Localisation Interior, underframe, roof etc	End [1] or [2]	Side Left [L] or Right [R]	Action Required (Ready to fix/pan needed NCR/ Work instruction required for special process remark)	Quality Sign-off	Prasa Sign-off	
1			Missing power on rmgweld									2	lre				

[illegible]

[illegible]

Train #	Car #	TC1	M1	M2	M3	M4	TC2	Process Stage	Inspector	Date	Page
200	N12								Benj/bozky	4/10/24	1 of 1
Item	Defect Code	Dement Class	Description of Defects	Localisation Interior, underframe, roof etc.	End [1] or [2]	Side Left [L] or Right [R]	Action Required (Ready to fix/Part needed/ NCR/ Work instruction required for special process rework)	Quality Sign-off	Prasa Sign-off		
1			Rust on Euf 1 LHS								
2			Paint damage by 14th		1-2 (+12)	R/L					
3			Paint Mismatch on Euf door Sealed joint on Finisher LHS Euf 1		2						

Train #	Car #	TC1	M1	M2	M3	M4	TC2	Process Stage	Inspector	Date	Page
20	M4								N Lively Ben	12/02/24	1 of 1
Item Code	Defect Class	Description of Defects	Localisation Interior, underframe, roof etc.	End [1] or [2]	Side Left [L] or Right [R]	Action Required (Ready to fix/Part needed NCR/ Work instruction required for special process remark)	Quality Sign-off	Praca Sign-off			
1		Paint damage due to lifting					[Signature]	[Signature]			
2		Missing Sealant End 2.		2	L/R		[Signature]	[Signature]			