

[illegible]

Train #	212	Car #	M4	TC1	M1	M2	M3	M4	TC2	Process Stage	PC02 FM020	Inspector	G. deen Amo	Date	2024/02/21	Page	OF																		
Item	Defect Code	Dement Class	Description of Defects									Localisation Interior, underframe, roof etc	End (1) or (2)	Side Left (L) or Right (R)	Action Required (Ready to fix/Part needed/ NCR/ Work instruction required for special process rework)	Quality Sign-off	Prasa Sign-off																		
1		C	Rust on EUFI (CB1230)									EUFI	1	R																					
2		C	Damaged sealant on UF panels (End 2 LHS)									Underframe	2	L																					

GIB0000000380

Rev A0

Defects Report

29/03/2017

4/5 Pages

[illegible]

Train #	Car #	M2	TC1	M1	M3	M4	TC2	Process Stage	FTD010 PC02	Inspector	Gideon + Amo	Date	Page
Item Code	Defect Class	Description of Defects	Localisation <small>Interior, underframe, roof etc.</small>	End <small>(1) or (2)</small>	Side <small>Left [L] or Right [R]</small>	Action Required <small>(Ready to fix/Part needed/ NCR/ Work instruction required for special process rework)</small>	Quality Sign-off	Prasa Sign-off					
1	Burn Through on tapping pad (C81220)	Finisher	2	R									
2	Hole on underframe (EUF) sealant C81070)	EUF	2	R									

[illegible]

Train #	212	Car #	TC2	TC1	M1	M2	M3	M4	Process Stage	FT1020 PC02	Inspector	Guiden + Ama	Date	21/02/24	Page	4/5
Item	Defect Code	Dement Class	Description of Defects							Localisation Interior, underframe, roof etc	End [1] or [2]	Side Left [L] or Right [R]	Action Required (Ready to fix/Part needed/ NCR/ Work instruction required for special process remove)	Quality Signed	Prasa Signed	
1		C	End 2 single window RHS lower module (CB1129) Pinhole on sidewall skin after rework of burn through							Sidewall	2	R				
2		C	Cracked Sealant on panels (End 2 LHS)							Underframe	2	L				
3		C	Foreign material under sealant (End 1 RHS)							11	1	R				
<div>Handwritten signature and date: 29/03/2017</div>																